#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.15

## SOURCE INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** SIR-001488 Address: 333 Burma Road **Date Inspected:** 18-Mar-2009

City: Oakland, CA 94607

OSM Arrival Time: 1900 **Project Name:** SAS Superstructure **OSM Departure Time:** 700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Changxing Dao, Shangha

**Quality Control Contact:** William (Bill) Oak **Quality Control Present:** Yes No

**Material transfer:** Yes No N/A **Sampled Items:** Yes No N/A **Stock Transfer:** N/A OK to Cut: N/A Yes No Yes No **Rebar Test Witness:** N/A **Delayed/Cancelled:** N/A Yes No Yes No

Other: Coatings Inspection

**Bridge No:** 34-0006 OBG 3AE, OBG 3AW, OBG 4AW, OBG 3BV **Component:** 

**Bid Item:** Lot No: 77, 78, 79 B265

### **Summary of Items Observed:**

On this date Caltrans Office of Structural Materials (OSM) Quality Assurance (QA) NACE III coating inspector, Mr. James Lumley arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island in Shanghai, China. The purpose of the coating inspections are to monitor the surface preparation and coating applications for the SAS Bay Bridge project. This QA NACE III coating inspector observed the following: .OBG 3AE

Work and repairs in process outside blast shop in fit up area behind tower fabrication shops. ZPMC performing sanding and screening operations to interior surfaces and also perform touch up painting with Interzinc 22. ZPMC QC representative monitoring ambient conditions and informing personnel of repair areas.

OBG 4AW, OBG 3BW, OBG 3AW

These three segments are still undergoing fit up and assembly operations behind tower fabrication shop. No coating repairs performed to damaged areas from the edge cutting process and heat affected zones

## **Summary of Conversations:**

No relevant conversations on this date.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang. (858) 699-9549, who represents the Office of Structural Materials for your project.

# SOURCE INSPECTION REPORT

(Continued Page 2 of 2)

Inspected By:	Lumley,James	Quality Assurance Inspector
Reviewed By:	Miller,Mark	QA Reviewer